

STANDARDS ASSOCIATION OF AUSTRALIA

Australian Standard**for****BASIC ENVIRONMENTAL PROCEDURES FOR ELECTROTECHNOLOGY**

Part 2—TESTS

TEST Kd—HYDROGEN SULPHIDE TEST FOR CONTACTS AND CONNECTIONS

This test shall be read in conjunction with AS 1099.1, General.

CONTENTS

	<i>Page</i>
FOREWORD	K-17
1 SCOPE AND OBJECT	K-18
2 GENERAL	K-18
3 TEST CHAMBER	K-18
4 TEST ATMOSPHERE	K-18
5 INITIAL MEASUREMENTS	K-18
6 CONDITIONING	K-18
7 FINAL MEASUREMENTS	K-18
8 INFORMATION TO BE GIVEN IN THE RELEVANT SPECIFICATION	K-19
 APPENDICES	
A Generation of the Conditioning Atmosphere	K-20
B Measurement of Contact Resistance	K-22

FOREWORD

The purpose of the test is to determine the influence of atmospheres containing hydrogen sulphide on the contact properties of silver and silver alloys, whether protected or unprotected, solid or plated over other metals. The test is intended to provide an accelerated means of assessing the contamination of silver and silver alloys used for contacts and connections. It is considered particularly suitable for comparison of products and materials. It is not however, suitable as a general corrosion test, i.e. it should not be used as a method of predicting the likely behaviour of contacts or connections in specific industrial atmospheres.

The test method of this industrial atmosphere test is technically identical with that of IEC 68-2-43:1976. Appendix B, which provides a method of measurement for electrical contact resistance has been added.

Background information on the subject of accelerated corrosion testing generally is provided in AS 1099.3.7.

TEST

1 SCOPE AND OBJECT. This standard method sets out a test procedure to determine the influence of atmospheres containing hydrogen sulphide on the contact properties of contacts made of—

- (a) silver or silver alloy;
 - (b) silver protected with another layer;
 - (c) other metals covered with silver or silver alloy;
- and to check wrapped or crimped connections made of the materials listed with regard to their continuity or effectiveness.

In all tests, the major criteria of performance will be the *change in contact resistance* caused by exposure to the hydrogen sulphide containing atmosphere.

2 GENERAL. This test is intended to provide an accelerated means of assessing the effects of the tarnishing of silver and silver alloys used for contacts and connections and is particularly suitable for giving information on a comparative basis. It is not suitable as a general corrosion test, i.e. it may not predict the behaviour of contacts or connections in specific industrial atmospheres.

3 TEST CHAMBER. The test chamber and its auxiliary parts shall be made of materials that do not react with or absorb hydrogen sulphide and which do not influence the corrosive effects of the test atmosphere. The test atmosphere shall be introduced to and leave the chamber through tubes of sufficiently large diameters such that the total flow through the chamber is at least three, but not more than five, changes of the atmosphere per hour. The exhaust from the chamber shall not be allowed to enter the laboratory.

The detailed construction of the chamber including the method of producing the test atmosphere is optional provided that—

- (a) the conditions in that part of the chamber occupied by the specimens are within the specified limits;
- (b) the specimens under test are protected from direct contact with the incoming gas flow;
- (c) arrangements are made to move the specimens through the test atmosphere at an average rate of 20 m/h to 60 m/h (approximately 6 mm/s to 17 mm/s) or alternatively to gently stir the atmosphere, obtaining a similar relative velocity between atmosphere and specimen;
- (d) condensation does not occur on the inside walls of the test chamber;
- (e) the test chamber is not exposed to direct sunlight and the level of illumination (provided by daylight or by incandescent or fluorescent lamps) measured within the test chamber at the site of any exposed surface is 50 lx to 300 lx.

An example of a suitable test chamber is given in Appendix A.

4 TEST ATMOSPHERE. The composition of the atmosphere within the test chamber shall satisfy the following conditions:

- (a) Hydrogen sulphide: 10 to 15 mm³/L.
- (b) Temperature : 25 ± 2°C.

- (c) Relative humidity: 75 ± 5 percent (see Note).

NOTE: The relative humidity is to be held as close as possible to 75 percent but must in no case exceed 80 percent nor fall below 70 percent.

The test atmosphere may be obtained by mixing hydrogen sulphide (from any convenient source) with air and water vapour in a way to ensure a homogeneous mixture. More than one mixing stage may be necessary to obtain a homogeneous distribution of the small quantity of hydrogen sulphide.

5 INITIAL MEASUREMENTS. The specimens under test shall not be cleaned in any way unless required by the manufacturer's instructions, the relevant specification, or agreed upon between the interested parties.

The relevant specification may require that before and after the test, variation of contact resistance measurements shall be carried out in combination with mechanical tests, e.g. shock or vibration tests.

The specimens shall be measured, mechanically checked and subjected to mechanical endurance as required by the relevant specification.

The contact resistance shall be measured by the low-open-circuit voltage method in order to avoid damage to films formed on contact surfaces. One such measuring method suitable for most purposes is given in Appendix B.

6 CONDITIONING. Prior to the commencement of the test, it shall be established by suitable measurements that stable conditions for the concentration of hydrogen sulphide, the temperature and the relative humidity have been achieved. Periodic checks shall be made during the test to ensure that these conditions are maintained.

Care shall be taken that the specimens are so placed that they do not come into contact with one another and that they do not shield one another from the test atmosphere.

Adequate precautions shall be taken to ensure that the contacts are not disturbed during the exposure period.

Specimens shall be exposed with contacts open and/or closed as prescribed in the relevant specification.

The loading or functioning of the specimens should be permitted when specified in the relevant specification.

The specimens shall be continuously exposed to the conditioning atmosphere for 4, 10 or 21 days as required by the relevant specification.

7 FINAL MEASUREMENTS. The specimens shall be removed from the chamber and stored under standard recovery conditions for not less than 1 h and not more than 2 h before contact resistance measurements are made. Adequate precautions shall be taken to ensure that the contacts are not disturbed. The method used for measuring the contact resistance should be the same as used for the initial measurement.

If the necessary measurements cannot be made within the specified time, the period of storage under